















<2019학년도 연구실(실험실습실) 정기점검에 따른 후속조치 결과보고서>

■ 조치완료 : 2020년 4월 7일(화)

연번	조치 前	조치 後	조치내용
1			9호관 201호 항공보안교육원 비상조명등 교체
2			9호관 201호 항공보안교육원 비상조명등 교체
3			9호관 201호 항공보안교육원 비상조명등 교체
4			9호관 201호 항공보안교육원 비상조명등 교체
5			9호관 301호 항공보안교육원 비상조명등 교체

연번	조치 前	조치 後	조치내용
6			9호관 401호 택권도실습실 비상조명등 교체
7			9호관 401호 택권도실습실 비상조명등 교체
8			9호관 401호 택권도실습실 비상조명등 교체
9			11호관 304호 피아노실습실 비상조명등 교체
10			11호관 401호 보육실습실 비상조명등 교체

연번	조치 前	조치 後	조치내용
11			2호관 235호 디지털미디어랩 소화기 교체
12			2호관 532호 항공통신실습실 소화기 교체
13			3호관 304호 승무원실습실 소화기 교체
14			6호관 301호 기본간호실습실 I 소화기 교체
15			6호관 401호 성인간호시뮬레이션실습실 소화기 교체

연번	조치 前	조치 後	조치내용
16			6호관 403호 PBL실 소화기 교체
17			6호관 404호 II 기본간호실습실 소화기 교체
18			6호관 421호 통합간호시뮬레이션실습실 소화기 교체
19			6호관 421호 통합간호시뮬레이션실습실 소화기 교체
20			8호관 510호 기초의학실습실 소화기 교체

연번	조치 前	조치 後	조치내용
21	 A photograph showing a red fire extinguisher on a yellow base in a room. To the left is a large yellow machine, and on the wall is a red fire alarm pull station.	 A photograph showing the same room after the fire extinguisher has been replaced. The new extinguisher is also on a yellow base.	8호관 601호 건축인테리어 CAD실 소화기 교체
22	 A photograph of a square ceiling diffuser in a room with a white tiled ceiling.	 A photograph showing the ceiling diffuser moved to a different location on the ceiling.	9호관 201호 검도실습실 감지기 이동 설치